

1

FEB 3 1981 RON Z.

- 1 Fire place not completed or fire blocked
- 2 Not Ready 3rd floor inap. as follows
- 3 Need Eng. report and drawing on hip roof areas
- 4 Need sway bracing hip roof area
- 5 Need proper support under porch headers
- 6 Fix MW corner of roof (hole)
- 7 Need access holes by final
- 8 Truss rim plates cut at 2 hr fire wall RON Z.