



City of Fort Collins
Engineering Department

REPORT OF NEW CONCRETE INSTALLATION

Subdivision or Project Beithang Knolls Phase II

Contractor C.G. & S.

Date Work Started 7-30-90

Date Work Completed 8-21-90 Inspector _____

Drive-over curb, gutter & walk Sidewalk: width _____

Vertical curb & gutter Radius: number 6 with Handicap Ramps

Drive-over curb & gutter Cross-pan: number 2

Other (specify) Mid walk Handi-
cap Ramps (3) Catch basin: number _____

Limits or Location of Work: Compton Rd E. - From tie in with intersection of
Edgeware & Compton Rd. Compton Rd. W. from tie in on South
with Compton Rd (existing) to ~~then~~ temp N. end -
Prescott St E end @ Compton Rd, W. end @ Compton Rd.

Total Linear Footage Installed (report for curb, gutter and/or sidewalk _____)

Compton Rd E. Leg. = 600 L.F. of Driveover curb gutter & walk.

Compton Rd W. Leg = 600 L.F of " " " "

Prescott St. = 1,125 L.F of " " " "

COMMENTS:

Checked by: J.D.M.